



Model DSD2...2HP
or DSD3...2HP



CONTROLLER
WITH 2 HIGH POWER ISOLATED RELAYS
AND SEPARATE SUPPLY FOR CONTROLLER

DW1


Model DSD2...2HP
or DSD3...2HP



WIRING FOR HIGH POWER HEATERS IN TWO BANKS
AND SEPARATE SUPPLY FOR CONTROLLER

DW2

Model DSD2...2HP
or DSD3...2HP




Model DSD2...2HP
or DSD3...2HP

WIRING FOR MIXED HIGH POWER LOADS
AND SEPARATE SUPPLY FOR CONTROLLER

DW3


Model DSD2...2HP
or DSD3...2HP



WIRING FOR HIGH POWER
LOADS WITH CONTACTOR

DW6


Model DSD2...2HP(or 2MP)
or DSD3...2HP(or 2MP)



WIRING FOR HIGH POWER AC MOTOR (OR OTHER LOAD)
USING 2 HIGH POWER RELAYS

DW7


Model DSD2...2HP
or DSD3...2HP



SIMPLE WIRING FOR
HEATERS THROUGH 2 HIGH POWER RELAYS

DW11


Model DSD2...1HP(or 1MP)
or DSD3...1HP(or 1MP)



WIRING FOR HIGH POWER AC MOTOR (OR OTHER LOAD)
USING 1 HIGH POWER RELAY ONLY

DW12

Model DSD2...2HP
or DSD3...2HP



WIRING FOR 2 HIGH POWER AC OR DC MOTORS
AND SEPARATE SUPPLY FOR CONTROLLER

DW8

